

Tel: +95 (0)1 533080
Tel: +95 (0)1 533030-039
AFS:VYYYYOYX VYYYYNYX
Fax: +95 (0)1 533085/533016
E-Mail: aiso@ais.gov.mm,
nof@ais.gov.mm

Department of Civil Aviation
International NOTAM Office
ATC Operations Building
Yangon International Airport, Yangon 11021
Myanmar

NOTAM LIST
Series B

01 Sep 2020

THE FOLLOWING NOTAM B SERIES ARE **STILL IN FORCE ON 01 September 2020 03:47:00 UTC**. NOTAM NOT INCLUDED IN THIS LIST HAVE EITHER BEEN CANCELLED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

NOF: VYYY / SERIES B

ENROUTE / GENERAL

VYYF(YANGON FIR)

B0202/20

From 2009100000 to 2009232359
NOTAMR B0201/20
E) NIL AIRAC PUBLICATION FOR EFFECTIVE
DATE 10 SEPTEMBER 2020

B0225/20

From 2009012330 to 2009040830
NOTAMN
D) 01-04 2330-0830
E) GUNFIRING EXERCISE WILL TAKE PLACE
THE COORDINATES OF THE DANGER ZONE(ZAYETGONE) AS FLW:
POINT(A) 204000N 0953000E
POINT(B) 204000N 0954600E
POINT(C) 205000N 0954600E
POINT(D) 205000N 0953000E
POINT(A) 204000N 0953000E
NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN THE
ABOVE MENTION DANGER ZONE. DURING HOURS OF ACTIVITY,
THE FOLLOWING AIR TRAFFIC SERVICES ROUTE IS REROUTED/NOT AVBL IN YGN FIR.
W15 NOT AVBL BELOW FL340 BETWEEN MANDALAY INTERNATIONAL AIRPORT VOR AND TDE VOR.

Lower Limit: GND Upper Limit: 33000 FT AGL

B0228/20

From 2009160000 to 2009170900
NOTAMN
D) 0000-0900
E) GUNFIRING EXERCISE WILL TAKE PLACE WITH THE FLW
DETAILS: THE COORDINATES OF DANGER ZONE
(TAUNGPULU) AS FLW:
POINT(A) 210000N 0954700E
POINT(B) 210000N 0955300E
POINT(C) 210900N 0955300E

POINT(D) 210900N 0954700E
POINT(A) 210000N 0954700E
NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN
THE ABOVE MENTIONED DANGER ZONE.

Lower Limit: GND **Upper Limit:** 28000 FT AGL

B0229/20

From 2009100040 to 2009110830
NOTAMR B0226/20
D) 0040-0830
E) GUNFIRING EXERCISE WILL TAKE PLACE
THE COORDINATES OF THE DANGER ZONE(KONDE-NANT KHON) AS FLW:
POINT(A) 211300N 0964800E
POINT(B) 211300N 0965200E
POINT(C) 211800N 0965200E
POINT(D) 211800N 0964800E
POINT(A) 211300N 0964800E
NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN
THE ABOVE MENTIONED DANGER ZONE.

Lower Limit: GND **Upper Limit:** 22000 FT AGL

B0230/20

From 2008271215 to 2009301729
NOTAMR B0194/20
E) COVID-19: PASSENGER RESTRICTION.
IN CONSIDERATION OF THE NEED TO LIMIT THE SPREAD OF COVID-19
BY AIR TRANSPORT AND TO PROTECT THE HEALTH OF AIR TRAVELERS
AND AVIATION PERSONNEL, THE DEPARTMENT OF CIVIL AVIATION
OF MYANMAR REQUIRES ALL AIRLINES OPERATING RELIEF FLIGHTS
TO MYANMAR TO ENSURE THAT TEMPERATURE SCREENING AND
OBSERVATION OF COVID-19 SYMPTOMS ARE CONDUCTED ON ALL
PASSENGERS BEFORE BOARDING . INTERMEDIATE APPROACH FIX A PASSENGER HAS A BODY
TEMPERATURE OF 100.4°F/38°C OR HIGHER OR PRESENTS SIGN(S)/
SYMPTOM(S) OF ACUTE RESPIRATORY ILLNESS, THE AIRLINE
CONCERNED SHALL DENY BOARDING TO SUCH PASSENGER AND
ADVISE HIM/HER TO DEFER HIS/HER TRAVEL AND SEEK MEDICAL ATTENTION.

B0231/20

From 2008271220 to 2009301729
NOTAMR B0195/20
E) COVID-19 : FLIGHT RESTRICTIONS
ALL AIR OPERATORS PROVIDING INTERNATIONAL AIR
SERVICES ARE ADVISED OF THE TEMPORARY MEASURES
FOR PREVENTION OF COVID-19 INFECTION IN MYANMAR
EFFECTIVE FROM 27 AUGUST 2020 1220 COORDINATED UNIVERSAL TIME TO 30 SEPTEMBER 2020
1729 COORDINATED UNIVERSAL TIME AS FOLLOWS:
1)LANDING AT ANY AIRPORT IN MYANMAR ARE NOT ALLOWED
FOR ALL INTERNATIONAL COMMERCIAL PASSENGER FLIGHTS:
2)ALL LANDING PERMISSIONS PREVIOUSLY GRANTED BY DCA
MYANMAR ARE SUSPENDED:
3) 1) AND 2) WILL NOT APPLY TO RELIEF FLIGHTS,
CARGO FLIGHTS,MEDICAL EVACUATION FLIGHTS AND
SPECIAL FLIGHTS SPECIFICALLY APPROVED BY DCA MYANMAR:
4) 1) WILL NOT APPLY TO:
A) AIRCRAFT IN STATE OF EMERGENCY:

B) TECHNICAL LANDING WITHOUT DISEMBARKING PASSENGERS.

5) PERSONS ON BOARD EXEMPTED FLIGHTS EXCEPT CREW SHALL NOT BE PERMITTED TO DISEMBARK WITHOUT AUTHORIZATION. CREW MEMBERS MAY DISEMBARK BUT SHALL BE SUBJECT TO QUARANTINE REQUIREMENTS OF THE MINISTRY OF HEALTH AND SPORTS DURING THEIR ROTATION / REST PERIOD:

6) ENR AIR TRAFFIC SERVICES IS NORMAL AND AIR OPERATORS ARE ABLE TO FILE VYYY AS ALTERNATE AERODROME.

B0232/20

From 2009010344 to 2010010344EST
NOTAMR B0197/20

E) CHECKLIST

YEAR=2019 0343

YEAR=2020 0167 0174 0198 0202 0216 0217 0218 0219 0225 0227 0228 0229 0230 0231

LATEST PUBLICATIONS

AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 1/20 EFFECTIVE FROM 16 JULY 2020

AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 5/19 EFFECTIVE FROM 10 OCTOBER 2019

AIP AMENDMENT 1/19 EFFECTIVE FROM 14 JANUARY 2019

AIP SUPPLEMENT 5/17 EFFECTIVE FROM 2 FEBRUARY 2017

AIC A3/20 EFFECTIVE FROM 3 JANUARY 2020

AERODROMES

VYNT(NAYPYITAW INTL)

B0218/20

From 2008180001 to 2011172359EST
NOTAMR B0154/20

E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO NAYPYITAW INTERNATIONAL AIRPORT IS DETECTED WITH SYMPTOMS COMPATIBLE WITH SEVERE RESPIRATORY DISEASE ASSOCIATED WITH NOVEL CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED. SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT AT RESPECTED AIRPORTS

VYCZ(MANDALAY/CHANMYATHAZI)

B0167/20

From 2006050442 to 2009042359EST
NOTAMN

E) MDY VOR/DME U/S DUE TO TECHNICAL REASON.

VYYY(YANGON INTL)

B0343/19

From 1912040000 to PERM
NOTAMN

E) VYYY AD NEW AIRCRAFT STAND 29 IS ESTABLISHED AND

OPERATED ON APRON B WITH THE FOLLOWING COORDINATES:
165405.05N 960734.04E

B0216/20

From 2008180001 to 2011172359EST
NOTAMR B0152/20
E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO
YANGON INTERNATIONAL AIRPORT IS DETECTED
WITH SYMPTOMS COMPATIBLE WITH SEVERE
RESPIRATORY DISEASE ASSOCIATED WITH NOVEL
CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY
ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT
WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED.
SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT
AT RESPECTED AIRPORTS

B0219/20

From 2008230001 to 2011222359EST
NOTAMR B0155/20
E) VYYY AD VISUAL DOCKING GUIDANCE SYSTEM
(VDGS)AT CONTACT STAND 3,4,5,6,7,8,9,10,11 NOT
AVBL DUE TO RENOVATION WIP

VYMD(MANDALAY INTL)

B0174/20

From 2006181150 to 2009160300
NOTAMN
E) VYMD ATIS (128.5 MHZ) U/S DUE TECHNICAL REASON

B0217/20

From 2008180001 to 2011172359EST
NOTAMR B0153/20
E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO
MANDALAY INTERNATIONAL AIRPORT IS DETECTED
WITH SYMPTOMS COMPATIBLE WITH SEVERE
RESPIRATORY DISEASE ASSOCIATED WITH NOVEL
CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY
ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT
WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED.
SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT
AT RESPECTED AIRPORTS

B0227/20

From 2008240629 to 2009202359
NOTAMR B0161/20
E) VYMD INTERNATIONAL AIRPORT FIRE FIGHTING CATEGORIES
CAT-9 TO CAT-7 DUE TO FIRE FIGHTER VEHICLE MAINTENANCE.

VYPN(PATHEIN)

B0198/20

From 2008030459 to 2011032359EST
NOTAMR B0139/20

Latest AIP Amendments:

AIRAC AIP AMDT 1/20 WEF 16 JUL 2020
AIP AMDT 1/19 WEF 14 JAN 2019

AIP Supplements in force:

AIRAC AIP SUP 1/03 WEF 27 NOV 2003
AIRAC AIP SUP 6/04 WEF 25 NOV 2004
AIRAC AIP SUP 31/09 WEF 17 DEC 2009
AIRAC AIP SUP 2/15 WEF 12 NOV 2015
AIRAC AIP SUP 6/17 WEF 20 JUL 2017
AIRAC AIP SUP 8/17 WEF 07 DEC 2017
AIRAC AIP SUP 4/18 WEF 29 MAR 2018
AIRAC AIP SUP 8/18 WEF 08 NOV 2018
AIRAC AIP SUP 9/18 WEF 08 NOV 2018
AIRAC AIP SUP 10/18 WEF 08 NOV 2018
AIRAC AIP SUP 11/18 WEF 06 DEC 2018
AIRAC AIP SUP 12/18 WEF 06 DEC 2018
AIRAC AIP SUP 14/18 WEF 03 JAN 2019
AIRAC AIP SUP 15/18 WEF 03 JAN 2019
AIRAC AIP SUP 16/18 WEF 03 JAN 2019
AIRAC AIP SUP 17/18 WEF 03 JAN 2019
AIRAC AIP SUP 18/18 WEF 03 JAN 2019
AIRAC AIP SUP 1/19 WEF 23 MAY 2019
AIRAC AIP SUP 2/19 WEF 23 MAY 2019
AIRAC AIP SUP 3/19 WEF 23 MAY 2019
AIRAC AIP SUP 4/19 WEF 23 MAY 2019
AIRAC AIP SUP 5/19 WEF 10 OCT 2019
AIP SUP 5/04 WEF 1 SEP 2004
AIP SUP 3/05 WEF 1 SEP 2005
AIP SUP 2/11 WEF 30 MAY 2011
AIP SUP 3/11 WEF 30 MAY 2011
AIP SUP 4/11 WEF 30 MAY 2011
AIP SUP 1/13 WEF 1 AUG 2013
AIP SUP 2/13 WEF 1 AUG 2013
AIP SUP 3/13 WEF 1 AUG 2013
AIP SUP 4/13 WEF 1 AUG 2013
AIP SUP 5/13 WEF 1 AUG 2013
AIP SUP 6/13 WEF 1 AUG 2013
AIP SUP 7/13 WEF 01 AUG 2013
AIP SUP 8/13 WEF 1 AUG 2013
AIP SUP 9/13 WEF 1 AUG 2013
AIP SUP 10/13 WEF 1 AUG 2013
AIP SUP 13/13 WEF 1 AUG 2013
AIP SUP 14/13 WEF 1 AUG 2013
AIP SUP 15/13 WEF 1 AUG 2013
AIP SUP 16/13 WEF 1 AUG 2013
AIP SUP 17/13 WEF 1 AUG 2013
AIP SUP 18/13 WEF 1 AUG 2013
AIP SUP 1/17 WEF 2 FEB 2017
AIP SUP 2/17 WEF 2 FEB 2017
AIP SUP 3/17 WEF 2 FEB 2017
AIP SUP 4/17 WEF 2 FEB 2017
AIP SUP 5/17 WEF 2 FEB 2017

AICs in force:

AIC A6/02 WEF 15 JUN 2002
AIC A8/02 WEF 28 NOV 2002
AIC A1/04 WEF 1 APR 2004
AIC A1/05 WEF 1 APR 2005
AIC A2/05 WEF 1 JUL 2005
AIC A5/05 WEF 15 JAN 2006
AIC A1/06 WEF 1 JAN 2006
AIC A1/07 WEF 1 FEB 2007
AIC A2/07 WEF 1 FEB 2007
AIC A3/07 WEF 1 FEB 2007
AIC A4/07 WEF 1 FEB 2007
AIC A5/07 WEF 1 SEP 2007
AIC A6/07 WEF 1 SEP 2007
AIC A7/07 WEF 1 SEP 2007
AIC A10/07 WEF 11 DEC 2007
AIC A1/09 WEF 1 JAN 2009
AIC A2/09 WEF 15 JAN 2009
AIC A1/12 WEF 1 JUL 2012
AIC A2/12 WEF 1 NOV 2012
AIC A3/12 WEF 1 NOV 2012
AIC A1/13 WEF 1 MAY 2013
AIC A1/14 WEF 01 AUG 2014
AIC A2/14 WEF 20 OCT 2014
AIC A2/16 WEF 23 JUN 2016
AIC A3/18 WEF 01 MAR 2018
AIC A3/19 WEF 28 MAR 2019
AIC A1/20 WEF 01 JAN 2020
AIC A2/20 WEF 01 JAN 2020
AIC A3/20 WEF 3 JAN 2020