

Tel: +95 (0)1 533080
Tel: +95 (0)1 533030-039
AFS:VYYYYOYX VYYYYNYX
Fax: +95 (0)1 533085/533016
E-Mail: aiso@ais.gov.mm,
nof@ais.gov.mm

Department of Civil Aviation
International NOTAM Office
ATC Operations Building
Yangon International Airport, Yangon 11021
Myanmar

NOTAM LIST
Series B

01 Oct 2020

THE FOLLOWING NOTAM B SERIES ARE **STILL IN FORCE ON 01 October 2020 02:51:33 UTC**. NOTAM NOT INCLUDED IN THIS LIST HAVE EITHER BEEN CANCELLED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

NOF: VYYY / SERIES B

ENROUTE / GENERAL

VYYF(YANGON FIR)

B0234/20

From 2010080000 to 2010212359

NOTAMN

E) TRIGGER NOTAM - PERMANENT AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 02/2020 EFFECTIVE FROM 08 OCTOBER 2020.

B0241/20

From 2009280100 to 2010030930

NOTAMN

D) 0100-0930

E) GUNFIRING EXERCISE WILL TAKE PLACE

THE COORDINATES OF THE DANGER ZONE(ZAYETGONE) AS FLW:

POINT(A) 204000N 0953000E

POINT(B) 204000N 0954600E

POINT(C) 205000N 0954600E

POINT(D) 205000N 0953000E

POINT(A) 204000N 0953000E

NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN THE ABOVE MENTION DANGER ZONE.

Lower Limit: GND Upper Limit: 33000 FT AGL

B0251/20

From 2011050000 to 2011182359

NOTAMN

E) NIL AIRAC PUBLICATION FOR EFFECTIVE DATE

05 NOVEMBER 2020

B0253/20

From 2009281239 to 2010311729

NOTAMR B0230/20

E) COVID-19: PASSENGER RESTRICTION.

IN CONSIDERATION OF THE NEED TO LIMIT THE SPREAD OF COVID-19

BY AIR TRANSPORT AND TO PROTECT THE HEALTH OF AIR TRAVELERS AND AVIATION PERSONNEL, THE DEPARTMENT OF CIVIL AVIATION OF MYANMAR REQUIRES ALL AIRLINES OPERATING RELIEF FLIGHTS TO MYANMAR TO ENSURE THAT TEMPERATURE SCREENING AND OBSERVATION OF COVID-19 SYMPTOMS ARE CONDUCTED ON ALL PASSENGERS BEFORE BOARDING . INTERMEDIATE APPROACH FIX A PASSENGER HAS A BODY TEMPERATURE OF 100.4F/38C OR HIGHER OR PRESENTS SIGN(S)/ SYMPTOM(S) OF ACUTE RESPIRATORY ILLNESS, THE AIRLINE CONCERNED SHALL DENY BOARDING TO SUCH PASSENGER AND ADVISE HIM/HER TO DEFER HIS/HER TRAVEL AND SEEK MEDICAL ATTENTION.

B0254/20

From 2009281249 to 2010311729

NOTAMR B0231/20

E) COVID-19 : FLIGHT RESTRICTIONS

ALL AIR OPERATORS PROVIDING INTERNATIONAL AIR SERVICES ARE ADVISED OF THE TEMPORARY MEASURES FOR PREVENTION OF COVID-19 INFECTION IN MYANMAR EFFECTIVE FROM 28 SEPTEMBER 2020 1249 COORDINATED UNIVERSAL TIME TO 31 OCTOBER 2020 1729 COORDINATED UNIVERSAL TIME AS FOLLOWS:

1) LANDING AT ANY AIRPORT IN MYANMAR ARE NOT ALLOWED FOR ALL INTERNATIONAL COMMERCIAL PASSENGER FLIGHTS:

2) ALL LANDING PERMISSIONS PREVIOUSLY GRANTED BY DCA MYANMAR ARE SUSPENDED:

3) 1) AND 2) WILL NOT APPLY TO RELIEF FLIGHTS, CARGO FLIGHTS, MEDICAL EVACUATION FLIGHTS AND SPECIAL FLIGHTS SPECIFICALLY APPROVED BY DCA MYANMAR:

4) 1) WILL NOT APPLY TO:

A) AIRCRAFT IN STATE OF EMERGENCY:

B) TECHNICAL LANDING WITHOUT DISEMBARKING PASSENGERS.

5) PERSONS ON BOARD EXEMPTED FLIGHTS EXCEPT CREW SHALL NOT BE PERMITTED TO DISEMBARK WITHOUT AUTHORIZATION. CREW MEMBERS MAY DISEMBARK BUT SHALL BE SUBJECT TO QUARANTINE REQUIREMENTS OF THE MINISTRY OF HEALTH AND SPORTS DURING THEIR ROTATION / REST PERIOD:

6) ENR AIR TRAFFIC SERVICES IS NORMAL AND AIR OPERATORS ARE ABLE TO FILE VYYY AS ALTERNATE AERODROME.

B0255/20

From 2009302330 to 2010031130

NOTAMN

D) 2330-1130

E) GUN FIRING EXERCISE WILL TAKE PLACE

THE COORDINATES OF THE DANGER ZONE (MALON AREA) AS FLW:

POINT(A) 194800 NORTHERN LATITUDE 0943300 E

POINT(B) 194800 NORTHERN LATITUDE 0951000 E

POINT(C) 195900 NORTHERN LATITUDE 0951000 E

POINT(D) 195900 NORTHERN LATITUDE 0943300 E

POINT(A) 194800 NORTHERN LATITUDE 0943300 E

NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN THE

ABOVE MENTIONED DANGER ZONE. DURING HOURS OF

ACTIVITY, THE FOLLOWING AIR TRAFFIC SERVICES ROUTES ARE REROUTED/NOT AVBL IN YANGON FIR.

01) W8, W12, W14, W15, W22 NOT AVBL.

Lower Limit: GND **Upper Limit:** UNL

B0256/20

From 2010020530 to 2010020830

NOTAMN

D) 0530-0830

E) GUNFIRING EXERCISE WILL TAKE PLACE THE COORDINATES OF THE DANGER ZONE(KONDE-NANT KHON)AS FOLLOWING:

POINT(A) 211300N 0964800E

POINT(B) 211300N 0965200E

POINT(C) 211800N 0965200E

POINT(D) 211800N 0964800E

POINT(A) 211300N 0964800E

NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN THE ABOVE MENTIONED DANGER ZONE.

Lower Limit: GND **Upper Limit:** 22000 FT AGL

B0257/20

From 2010142330 to 2010161130

NOTAMN

D) 2330-1130

E) GUNFIRING EXERCISE WILL TAKE PLACE WITH THE FOLLOWING DETAILS: THE COORDINATES OF THE DANGER ZONE(TAUNG NYO AREA) AS FOLLOWS:

POINT(A) 195200N 0960300E

POINT(B) 195200N 0960900E

POINT(C) 200300N 0960900E

POINT(D) 200300N 0960900E

POINT(A) 195200N 0960300E

NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN THE ABOVE MENTIONED DANGER ZONE. DURING HOURS OF ACTIVITY, THE FOLLOWING AIR TRAFFIC SERVICES ROUTE IS REROUTED/NOT AVBL IN YANGON FIR.
01) W13 NOT AVBL BELOW FL210 BETWEEN NPT VOR AND MANDALAY INTERNATIONAL AIRPORT VOR.
(BIDIRECTIONAL)

Lower Limit: GND **Upper Limit:** 20000FT AGL

B0258/20

From 2010010249 to 2011010249EST

NOTAMR B0232/20

E) CHECKLIST

YEAR=2019 0343

YEAR=2020 0198 0216 0217 0218 0219 0233 0234 0236 0241 0243 0245 0246 0248 0251 0253 0254 0255 0256 0257

LATEST PUBLICATIONS

AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 2/20 EFFECTIVE FROM 8 OCTOBER 2020

AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 5/19 EFFECTIVE FROM 10 OCTOBER 2019

AIP AMENDMENT 1/19 EFFECTIVE FROM 14 JANUARY 2019

AIP SUPPLEMENT 5/17 EFFECTIVE FROM 2 FEBRUARY 2017

AIC A3/20 EFFECTIVE FROM 3 JANUARY 2020

AERODROMES

VYNT(NAYPYITAW INTL)

B0218/20

From 2008180001 to 2011172359EST

NOTAMR B0154/20

E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO NAYPYITAW INTERNATIONAL AIRPORT IS DETECTED WITH SYMPTOMS COMPATIBLE WITH SEVERE RESPIRATORY DISEASE ASSOCIATED WITH NOVEL CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED. SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT AT RESPECTED AIRPORTS

VY CZ(MANDALAY/CHANMYATHAZI)

B0233/20

From 2009050001 to 2012042359EST
NOTAMR B0167/20
E) MDY VOR/DME U/S DUE TO TECHNICAL REASON.

VYYY(YANGON INTL)

B0343/19

From 1912040000 to PERM
NOTAMN
E) VYYY AD NEW AIRCRAFT STAND 29 IS ESTABLISHED AND OPERATED ON APRON B WITH THE FOLLOWING COORDINATES:
165405.05N 960734.04E

B0216/20

From 2008180001 to 2011172359EST
NOTAMR B0152/20
E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO YANGON INTERNATIONAL AIRPORT IS DETECTED WITH SYMPTOMS COMPATIBLE WITH SEVERE RESPIRATORY DISEASE ASSOCIATED WITH NOVEL CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED. SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT AT RESPECTED AIRPORTS

B0219/20

From 2008230001 to 2011222359EST
NOTAMR B0155/20
E) VYYY AD VISUAL DOCKING GUIDANCE SYSTEM (VDGS) AT CONTACT STAND 3,4,5,6,7,8,9,10,11 NOT AVBL DUE TO RENOVATION WIP

B0236/20

From 2009091730 to 2010162230
NOTAMN
D) 1730-2230 EXC SAT SUN
E) VYYY AD CLOSED DUE TO RUNWAY AND TAXIWAY MARKING REPAINTING AND REPAIRING WIP.

VYMD(MANDALAY INTL)

B0217/20

From 2008180001 to 2011172359EST

NOTAMR B0153/20

E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO MANDALAY INTERNATIONAL AIRPORT IS DETECTED WITH SYMPTOMS COMPATIBLE WITH SEVERE RESPIRATORY DISEASE ASSOCIATED WITH NOVEL CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED. SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT AT RESPECTED AIRPORTS

B0243/20

From 2009210001 to 2010202359EST

NOTAMR B0227/20

E) VYMD INTERNATIONAL AIRPORT FIRE FIGHTING CATEGORIES CAT-9 TO CAT-7 DUE TO FIRE FIGHTER VEHICLE MAINTENANCE.

VYPN(PATHEIN)

B0198/20

From 2008030459 to 2011032359EST

NOTAMR B0139/20

E) VYPN AD DME U/S DUE TECHNICAL PROBLEM.

VYFS(SURBUNG AIRPORT)

B0245/20

From 2010080000 to PERM

NOTAMN

E) AERODROME TRAFFIC ZONE VERTICAL LIMITS AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 02/2020 PART AD
VYFS 2.17 SURBUNG AERODROME TRAFFIC ZONE READ 8000 FEET ABOVE MEAN SEA LEVEL INSTEAD OF 2000 FEET ABOVE MEAN SEA LEVEL.

B0246/20

From 2010080000 to PERM

NOTAMN

E) CONTROL ZONE VERTICAL LIMITS AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 02/2020 PART AD
VYFS 2.17 SURBUNG CONTROL ZONE READ FL150 STANDARD INSTEAD OF FL130 STANDARD

B0248/20

From 2010080000 to PERM

NOTAMN

E) RUNWAY 36 TRUE AND MAGNETIC BEARING AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 02/2020 PART
AD VYFS 2.12 RUNWAY 36 READ 357.00 DEGREES INSTEAD OF 3570.00 DEGREES

Latest AIP Amendments:

AIRAC AIP AMDT 2/20 WEF 8 OCT 2020
AIP AMDT 1/19 WEF 14 JAN 2019

AIP Supplements in force:

AIRAC AIP SUP 1/03 WEF 27 NOV 2003
AIRAC AIP SUP 6/04 WEF 25 NOV 2004
AIRAC AIP SUP 31/09 WEF 17 DEC 2009
AIRAC AIP SUP 2/15 WEF 12 NOV 2015
AIRAC AIP SUP 6/17 WEF 20 JUL 2017
AIRAC AIP SUP 8/17 WEF 07 DEC 2017
AIRAC AIP SUP 4/18 WEF 29 MAR 2018
AIRAC AIP SUP 8/18 WEF 08 NOV 2018
AIRAC AIP SUP 9/18 WEF 08 NOV 2018
AIRAC AIP SUP 10/18 WEF 08 NOV 2018
AIRAC AIP SUP 11/18 WEF 06 DEC 2018
AIRAC AIP SUP 12/18 WEF 06 DEC 2018
AIRAC AIP SUP 14/18 WEF 03 JAN 2019
AIRAC AIP SUP 15/18 WEF 03 JAN 2019
AIRAC AIP SUP 16/18 WEF 03 JAN 2019
AIRAC AIP SUP 17/18 WEF 03 JAN 2019
AIRAC AIP SUP 18/18 WEF 03 JAN 2019
AIRAC AIP SUP 1/19 WEF 23 MAY 2019
AIRAC AIP SUP 2/19 WEF 23 MAY 2019
AIRAC AIP SUP 3/19 WEF 23 MAY 2019
AIRAC AIP SUP 4/19 WEF 23 MAY 2019
AIRAC AIP SUP 5/19 WEF 10 OCT 2019
AIP SUP 5/04 WEF 1 SEP 2004
AIP SUP 3/05 WEF 1 SEP 2005
AIP SUP 2/11 WEF 30 MAY 2011
AIP SUP 3/11 WEF 30 MAY 2011
AIP SUP 4/11 WEF 30 MAY 2011
AIP SUP 1/13 WEF 1 AUG 2013
AIP SUP 2/13 WEF 1 AUG 2013
AIP SUP 3/13 WEF 1 AUG 2013
AIP SUP 4/13 WEF 1 AUG 2013
AIP SUP 5/13 WEF 1 AUG 2013
AIP SUP 6/13 WEF 1 AUG 2013
AIP SUP 7/13 WEF 01 AUG 2013
AIP SUP 8/13 WEF 1 AUG 2013
AIP SUP 9/13 WEF 1 AUG 2013
AIP SUP 10/13 WEF 1 AUG 2013
AIP SUP 13/13 WEF 1 AUG 2013
AIP SUP 14/13 WEF 1 AUG 2013
AIP SUP 15/13 WEF 1 AUG 2013
AIP SUP 16/13 WEF 1 AUG 2013
AIP SUP 17/13 WEF 1 AUG 2013
AIP SUP 18/13 WEF 1 AUG 2013
AIP SUP 1/17 WEF 2 FEB 2017
AIP SUP 2/17 WEF 2 FEB 2017
AIP SUP 3/17 WEF 2 FEB 2017
AIP SUP 4/17 WEF 2 FEB 2017
AIP SUP 5/17 WEF 2 FEB 2017

AICs in force:

AIC A6/02 WEF 15 JUN 2002
AIC A8/02 WEF 28 NOV 2002
AIC A1/04 WEF 1 APR 2004
AIC A1/05 WEF 1 APR 2005

AIC A2/05 WEF 1 JUL 2005
AIC A5/05 WEF 15 JAN 2006
AIC A1/06 WEF 1 JAN 2006
AIC A1/07 WEF 1 FEB 2007
AIC A2/07 WEF 1 FEB 2007
AIC A3/07 WEF 1 FEB 2007
AIC A4/07 WEF 1 FEB 2007
AIC A5/07 WEF 1 SEP 2007
AIC A6/07 WEF 1 SEP 2007
AIC A7/07 WEF 1 SEP 2007
AIC A10/07 WEF 11 DEC 2007
AIC A1/09 WEF 1 JAN 2009
AIC A2/09 WEF 15 JAN 2009
AIC A1/12 WEF 1 JUL 2012
AIC A2/12 WEF 1 NOV 2012
AIC A3/12 WEF 1 NOV 2012
AIC A1/13 WEF 1 MAY 2013
AIC A1/14 WEF 01 AUG 2014
AIC A2/14 WEF 20 OCT 2014
AIC A2/16 WEF 23 JUN 2016
AIC A3/18 WEF 01 MAR 2018
AIC A3/19 WEF 28 MAR 2019
AIC A1/20 WEF 01 JAN 2020
AIC A2/20 WEF 01 JAN 2020
AIC A3/20 WEF 3 JAN 2020