

**Tel: +95 (0)1 533080**  
**Tel: +95 (0)1 533030-039**  
**AFS:VYYYYOYX VYYYYNYX**  
**Fax: +95 (0)1 533085/533016**  
**E-Mail: aiso@ais.gov.mm,**  
**nof@ais.gov.mm**

Department of Civil Aviation  
**International NOTAM Office**  
ATC Operations Building  
Yangon International Airport, Yangon 11021  
Myanmar

**NOTAM LIST**  
**Series C**

**01 Nov 2020**

THE FOLLOWING NOTAM C SERIES ARE **STILL IN FORCE ON 01 November 2020 06:05:24 UTC**. NOTAM NOT INCLUDED IN THIS LIST HAVE EITHER BEEN CANCELLED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

## **NOF: VYYY / SERIES C**

### **ENROUTE / GENERAL**

#### **VYYF(YANGON FIR)**

##### **C0467/20**

From 2011050000 to 2011182359  
NOTAMN  
E) NIL AIRAC PUBLICATION FOR EFFECTIVE DATE  
05 NOVEMBER 2020

##### **C0514/20**

From 2010211230 to 2011061630  
NOTAMN  
D) 1230-1630  
E) MAF,NIGHT FLYING EXERCISE WITH NIGHT VISION GOGGLE  
WILL BE CARRIED OUT BY-MI-35P HELICOPTER WILL TAKE  
PLACE AT VYNT.RESERVED AD :VYTO

**Lower Limit:** GND      **Upper Limit:** 3000FT AGL

##### **C0518/20**

From 2010300100 to 2011030830  
NOTAMN  
D) 0100-0830  
E) GUNFIRING EXERCISE WILL TAKE PLACE WITH THE FLW  
DETAILS:THE COORDS OF THE DANGER ZONE (HTANTABIN)  
AREA AS FOLLOWS:  
POINT(A)185000N 0963000E  
POINT(B)185000N 0963500E  
POINT(C)185500N 0963500E  
POINT(D)185500N 0963000E  
POINT(A)185000N 0963000E  
NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN  
THE ABOVE MENTION DANGER ZONE.  
1)W13 NOT AVBL BELOW FL160 BETWEEN NPT VOR AND  
MIA VOR.(BIDIRECTIONAL)

**Lower Limit:** GND      **Upper Limit:** 15000 FT AGL

**C0529/20**

From 2012030000 to 2012162359  
NOTAMN  
E) NIL AIRAC PUBLICATION FOR EFFECTIVE DATE  
03 DECEMBER 2020

**C0531/20**

From 2010261130 to 2011041630  
NOTAMN  
D) 1130-1630  
E) MAF,BEFORE SUNSET TIME EXERCISE AND NIGHT  
FLYING EXERCISE FLIGHT CARRIED OUT BY  
MIG-29 ACFT,WILL TAKE PLACE AT VYTO  
(TAUNGGU)AND MYANMAR AIR FORCE TRAINING AREA.  
RESERVED AD:VYMW,VYMD,(MIA)SHANTE,VYYY  
AND VYNT.

**Lower Limit:** GND      **Upper Limit:** 6000FT AGL

**C0532/20**

From 2010261300 to 2011041630  
NOTAMN  
D) 1300-1630  
E) MYANMAR AIR FORCE NIGHT VISION GOGGLE EXERCISE FLIGHT  
CARRIED OUT BY MI-17 HELICOPTER,WILL TAKE  
PLACE AT VYHB(HMAWBI)AND MYANMAR AIR FORCE TRAINING  
AREA.  
RESERVED AD:VYYY

**Lower Limit:** GND      **Upper Limit:** 1000 FT AGL

**C0539/20**

From 2010271155 to 2011301729  
NOTAMR C0469/20  
E) COVID-19: PASSENGER RESTRICTION.  
IN CONSIDERATION OF THE NEED TO LIMIT THE SPREAD OF  
COVID-19 BY AIR TRANSPORT AND TO PROTECT THE HEALTH  
OF AIR TRAVELERS AND AVIATION PERSONNEL,  
THE DEPARTMENT OF CIVIL AVIATION OF MYANMAR  
REQUIRES ALL AIRLINES OPERATING RELIEF FLIGHTS  
TO MYANMAR TO ENSURE THAT TEMPERATURE SCREENING  
AND OBSERVATION OF COVID-19 SYMPTOMS ARE CONDUCTED  
ON ALL PASSENGERS BEFORE BOARDING . INTERMEDIATE APPROACH FIX A PASSENGER  
HAS A BODY TEMPERATURE OF 100.4°F/38°C OR HIGHER OR  
PRESENTS SIGN(S)/SYMPTOM(S) OF ACUTE RESPIRATORY  
ILLNESS, THE AIRLINE CONCERNED SHALL DENY BOARDING  
TO SUCH PASSENGER AND ADVISE HIM/HER TO DEFER HIS/HER  
TRAVEL AND SEEK MEDICAL ATTENTION.

**C0540/20**

From 2010271210 to 2011301729  
NOTAMR C0470/20  
E) COVID-19 : FLIGHT RESTRICTIONS  
ALL AIR OPERATORS PROVIDING INTERNATIONAL AIR  
SERVICES ARE ADVISED OF THE TEMPORARY MEASURES

FOR PREVENTION OF COVID-19 INFECTION IN MYANMAR  
EFFECTIVE FROM 27 OCTOBER 2020 1210 COORDINATED UNIVERSAL TIME TO 30 NOVEMBER 2020

1729 COORDINATED UNIVERSAL TIME AS FOLLOWS:

1) LANDING AT ANY AIRPORT IN MYANMAR ARE NOT ALLOWED  
FOR ALL INTERNATIONAL COMMERCIAL PASSENGER FLIGHTS:

2) ALL LANDING PERMISSIONS PREVIOUSLY GRANTED BY DCA  
MYANMAR ARE SUSPENDED:

3) 1) AND 2) WILL NOT APPLY TO RELIEF FLIGHTS,  
CARGO FLIGHTS, MEDICAL EVACUATION FLIGHTS AND  
SPECIAL FLIGHTS SPECIFICALLY APPROVED BY DCA MYANMAR:

4) 1) WILL NOT APPLY TO:

A) AIRCRAFT IN STATE OF EMERGENCY:

B) TECHNICAL LANDING WITHOUT DISEMBARKING  
PASSENGERS.

5) PERSONS ON BOARD EXEMPTED FLIGHTS EXCEPT CREW  
SHALL NOT BE PERMITTED TO DISEMBARK WITHOUT  
AUTHORIZATION. CREW MEMBERS MAY DISEMBARK BUT  
SHALL BE SUBJECT TO QUARANTINE REQUIREMENTS OF THE  
MINISTRY OF HEALTH AND SPORTS DURING THEIR ROTATION /  
REST PERIOD:

6) ENR AIR TRAFFIC SERVICES IS NORMAL AND AIR OPERATORS ARE ABLE TO FILE  
VYYYY AS ALTERNATE AERODROME.

### **C0543/20**

From 2011010335 to 2012010335EST

NOTAMR C0480/20

E) CHECKLIST

YEAR=2020 0361 0362 0363 0364 0390 0393 0394 0395 0396 0407 0412 0413 0417 0429 0430 0431 0437 0455 0459  
0460 0462 0467 0482 0484 0485 0492 0502 0505 0510 0514 0518 0522 0529 0530 0531 0532 0538 0539 0540 0541  
LATEST PUBLICATIONS

AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 2/20 EFFECTIVE FROM 8 OCTOBER 2020

AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 5/19 EFFECTIVE FROM 10 OCTOBER  
2019

AIP AMENDMENT 1/19 EFFECTIVE FROM 14 JANUARY 2019

AIP SUPPLEMENT 5/17 EFFECTIVE FROM 2 FEBRUARY 2017

AIC A3/20 EFFECTIVE FROM 3 JANUARY 2020

## **AERODROMES**

### **VYNT(NAYPYITAW INTL)**

#### **C0394/20**

From 2008180001 to 2011172359EST

NOTAMR C0258/20

E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO  
NAYPYITAW INTERNATIONAL AIRPORT IS DETECTED  
WITH SYMPTOMS COMPATIBLE WITH SEVERE  
RESPIRATORY DISEASE ASSOCIATED WITH NOVEL  
CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY  
ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT  
WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED.  
SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT  
AT RESPECTED AIRPORTS

### **VYCZ(MANDALAY/CHANMYATHAZI)**

#### **C0429/20**

From 2009050001 to 2012042359EST  
NOTAMR C0291/20  
E) MDY VOR/DME U/S DUE TO TECHNICAL REASON.

**VYBP(BOKPYINN)**

**C0502/20**

From 2010140001 to 2101132359EST  
NOTAMR C0335/20  
E) VYBP AD RWY35 THRESHOLD DISPLACED 2500FT X 100FT  
WORK IF NOT POSSIBLE ROGRESS. RUNWAY AVBL LENGTH 7500FT X 100FT.  
PILOTS EXERCISE CAUTION LANDING AND TAKEOFF.

**VYHL(HOMMALINN)**

**C0412/20**

From 2008230001 to 2011222359EST  
NOTAMR C0265/20  
E) VYHL AD AWS U/S DUE TO TECHNICAL REASON. PILOTS EXERCISE CAUTION LANDING AND EXERCISE  
CAUTION TAKE-OFF.

**C0430/20**

From 2009050001 to 2012042359EST  
NOTAMR C0289/20  
E) VYHL AD NDB 255KHZ U/S DUE TO TECHNICAL REASON.

**VYKU(KYAUKTU)**

**C0485/20**

From 2010040501 to 2101032359EST  
NOTAMR C0327/20  
E) VYKU AD LEFT SIDE OF RUNWAY 04,NEW TWY  
(750 X 75)FT AND APRON (250 X 150)FT WIP.

**C0505/20**

From 2010140001 to 2101152359EST  
NOTAMN  
E) VYKU AD LEFT SIDE OF RUNWAY 04,TAXIWAY  
(750 X 75)FT AND APRON (250 X 150)FT WIP.

**VYPU(PAKHOKKU)**

**C0363/20**

From 2008030448 to 2011022359EST  
NOTAMR C0233/20  
E) VYPU AD AWOS U/S DUE TO TECHNICAL REASON .

**VYTD(THANDWE)**

**C0362/20**

From 2008030448 to 2011022359EST  
NOTAMR C0234/20  
E) VYTD AD NDB 270KHZ U/S DUE TECHNICAL REASON PROBLEM.

**C0390/20**

From 2008170001 to 2011162359EST  
NOTAMR C0256/20  
E) VYTD AD NIGHT LANDING FACILITIES NOT AVBL DUE TO  
RWY MIDDLE PORTION (4000 X 100 FT) WIP

**C0431/20**

From 2009050001 to 2012042359EST  
NOTAMR C0293/20  
E) VYTD AD DISPLACE THRD 2000 FEET X 100 FEET FROM THE RUNWAY 20  
AVBL LENGTH 6000 FEET X 100 FEET DUE TO RUNWAY WIP

**VYDW(DAWEI)**

**C0417/20**

From 2008250640 to 2011242359EST  
NOTAMR C0267/20  
E) VYDW AD NDB U/S DUE TECHNICAL REASON.

**C0437/20**

From 2009080358 to 2012072359EST  
NOTAMR C0296/20  
E) VYDW AD AWOS U/S DUE TECHNICAL REASON.

**VYMM(MAWLAMYINE)**

**C0413/20**

From 2008230001 to 2011222359EST  
NOTAMR C0266/20  
E) VYMM AD NIGHT LANDING FACILITIES NOT AVBL DUE TO TECH PROBLEM.

**C0455/20**

From 2009220001 to 2012212359EST  
NOTAMR C0308/20  
E) VYMM A/P RELOCATION OF HIGH-TENSION POWER LINE  
MAST IS IN PROGRESS 1.2NM FROM RUN-WAY 22 SIDE. ALL  
ACFTS AND HELICOPTERS ARE EXERCISE CAUTION LANDING AND EXERCISE CAUTION TAKE-OFF.

**VYME(MYEIK)**

**C0364/20**

From 2008030448 to 2011022359EST  
NOTAMR C0235/20  
E) VYME AD GLIDE SLOPE ANTENNA MAST HEIGHT ABOVE 50FT  
AT DIS 350FT FROM WEST OF RUNWAY CENTER LINE  
AND 1000FT FROM RUNWAY 18 THRESHOLD DUE INSTALL WIP.  
PILOTS ECL/ECT.)

**VYYY(YANGON INTL)**

**C0393/20**

From 2008180001 to 2011172359EST

NOTAMR C0257/20

E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO YANGON INTERNATIONAL AIRPORT IS DETECTED WITH SYMPTOMS COMPATIBLE WITH SEVERE RESPIRATORY DISEASE ASSOCIATED WITH NOVEL CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED. SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT AT RESPECTED AIRPORTS

**C0396/20**

From 2008230001 to 2011222359EST

NOTAMR C0260/20

E) VYYY AD VISUAL DOCKING GUIDANCE SYSTEM (VDGS)AT CONTACT STAND 3,4,5,6,7,8,9,10,11 NOT AVBL DUE TO RENOVATION WIP

**VYBM(BANMAW)**

**C0530/20**

From 2010220425 to 2101212359EST

NOTAMR C0343/20

E) VYBM AD AWOS U/S DUE TO TECHNICAL PROBLEM.

**VYLS(LASHIO)**

**C0407/20**

From 2008200918 to 2011192359EST

NOTAMN

E) VYLS AD RUNWAY LIGHT U/S DUE TECHNICAL REASON

**VYPT(PUTAO)**

**C0492/20**

From 2010080927 to 2101072359EST

NOTAMN

E) VYPT AD AWOS U/S DUE TO TECHNICAL REASON.

**VYMD(MANDALAY INTL)**

**C0395/20**

From 2008180001 to 2011172359EST

NOTAMR C0259/20

E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO MANDALAY INTERNATIONAL AIRPORT IS DETECTED WITH SYMPTOMS COMPATIBLE WITH SEVERE RESPIRATORY DISEASE ASSOCIATED WITH NOVEL CORONAVIRUS THE PILOT-IN-COMMAND SHALL NOTIFY ATC ON FIRST CONTACT OR INTERMEDIATE APPROACH FIX ALREADY IN CONTACT WITH AIR TRAFFIC CONTROL AS SOON AS SYMPTOMS ARE OBSERVED. SO THAT AIR TRAFFIC CONTROL CAN ALERT THE HEALTH DEPARTMENT AT RESPECTED AIRPORTS

**C0522/20**

From 2010200427 to 2011202359

NOTAMR C0451/20

E) VYMD INTERNATIONAL AIRPORT FIRE FIGHTING CATEGORIES  
CAT-9 TO CAT-7 DUE TO FIRE FIGHTER VEHICLE MAINTENANCE.

**C0541/20**

From 2010280846 to 2101272359EST

NOTAMN

E) VYMD RUNWAY 17 DME U/S DUE TECHNICAL REASON

**VYKI(KANTI)**

**C0482/20**

From 2010040452 to 2101032359EST

NOTAMN

E) VYKI STATION NDB U/S DUE TO TECHNICAL REASON.

**C0484/20**

From 2010040456 to 2101032359EST

NOTAMN

E) VYKI STATION AWOS U/S DUE TO TECHNICAL REASON.

**VYPN(PATHEIN)**

**C0361/20**

From 2008040001 to 2011032359EST

NOTAMR C0232/20

E) VYPN AD DME U/S DUE TECHNICAL PROBLEM.

**C0510/20**

From 2010150413 to 2011142359EST

NOTAMN

E) VYPN AD VOR 115.6 MHZ U/S DUE TO TECH PROBLEM.

**C0538/20**

From 2010260808 to 2101252359EST

NOTAMN

E) VYPN AD AWOS U/S DUE TECHNICAL PROBLEM.

**VYFS(SURBUNG AIRPORT)**

**C0459/20**

From 2010080000 to PERM

NOTAMN

E) AERODROME TRAFFIC ZONE VERTICAL LIMITS AIRAC AERONAUTICAL INFORMATION PUBLICATION  
AMENDMENT 02/2020 PART AD

VYFS 2.17 SURBUNG AERODROME TRAFFIC ZONE READ 8000 FEET ABOVE MEAN SEA LEVEL INSTEAD OF  
2000 FEET ABOVE MEAN SEA LEVEL.

**C0460/20**

From 2010080000 to PERM

NOTAMN

E) CONTROL ZONE VERTICAL LIMITS AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT  
02/2020 PART AD  
VYFS 2.17 SURBUNG CONTROL ZONE READ FL150 STANDARD INSTEAD OF  
FL130 STANDARD

**C0462/20**

From 2010080000 to PERM  
NOTAMN

E) RUNWAY 36 TRUE AND MAGNETIC BEARING AIRAC AERONAUTICAL INFORMATION PUBLICATION  
AMENDMENT 02/2020 PART  
AD VYFS 2.12 RUNWAY 36 READ 357.00 DEGREES INSTEAD OF 3570.00 DEGREES

---

**Latest AIP Amendments:**

AIRAC AIP AMDT 2/20 WEF 8 OCT 2020  
AIP AMDT 1/19 WEF 14 JAN 2019

**AIP Supplements in force:**

AIRAC AIP SUP 1/03 WEF 27 NOV 2003  
AIRAC AIP SUP 6/04 WEF 25 NOV 2004  
AIRAC AIP SUP 31/09 WEF 17 DEC 2009  
AIRAC AIP SUP 2/15 WEF 12 NOV 2015  
AIRAC AIP SUP 6/17 WEF 20 JUL 2017  
AIRAC AIP SUP 8/17 WEF 07 DEC 2017  
AIRAC AIP SUP 4/18 WEF 29 MAR 2018  
AIRAC AIP SUP 8/18 WEF 08 NOV 2018  
AIRAC AIP SUP 9/18 WEF 08 NOV 2018  
AIRAC AIP SUP 10/18 WEF 08 NOV 2018  
AIRAC AIP SUP 11/18 WEF 06 DEC 2018  
AIRAC AIP SUP 12/18 WEF 06 DEC 2018  
AIRAC AIP SUP 14/18 WEF 03 JAN 2019  
AIRAC AIP SUP 15/18 WEF 03 JAN 2019  
AIRAC AIP SUP 16/18 WEF 03 JAN 2019  
AIRAC AIP SUP 17/18 WEF 03 JAN 2019  
AIRAC AIP SUP 18/18 WEF 03 JAN 2019  
AIRAC AIP SUP 1/19 WEF 23 MAY 2019  
AIRAC AIP SUP 2/19 WEF 23 MAY 2019  
AIRAC AIP SUP 3/19 WEF 23 MAY 2019  
AIRAC AIP SUP 4/19 WEF 23 MAY 2019  
AIRAC AIP SUP 5/19 WEF 10 OCT 2019  
AIP SUP 5/04 WEF 1 SEP 2004  
AIP SUP 3/05 WEF 1 SEP 2005  
AIP SUP 2/11 WEF 30 MAY 2011  
AIP SUP 3/11 WEF 30 MAY 2011  
AIP SUP 4/11 WEF 30 MAY 2011  
AIP SUP 1/13 WEF 1 AUG 2013  
AIP SUP 2/13 WEF 1 AUG 2013  
AIP SUP 3/13 WEF 1 AUG 2013  
AIP SUP 4/13 WEF 1 AUG 2013  
AIP SUP 5/13 WEF 1 AUG 2013  
AIP SUP 6/13 WEF 1 AUG 2013  
AIP SUP 7/13 WEF 01 AUG 2013  
AIP SUP 8/13 WEF 1 AUG 2013  
AIP SUP 9/13 WEF 1 AUG 2013  
AIP SUP 10/13 WEF 1 AUG 2013  
AIP SUP 13/13 WEF 1 AUG 2013  
AIP SUP 14/13 WEF 1 AUG 2013  
AIP SUP 15/13 WEF 1 AUG 2013



AIP SUP 16/13 WEF 1 AUG 2013  
AIP SUP 17/13 WEF 1 AUG 2013  
AIP SUP 18/13 WEF 1 AUG 2013  
AIP SUP 1/17 WEF 2 FEB 2017  
AIP SUP 2/17 WEF 2 FEB 2017  
AIP SUP 3/17 WEF 2 FEB 2017  
AIP SUP 4/17 WEF 2 FEB 2017  
AIP SUP 5/17 WEF 2 FEB 2017

**AICs in force:**

AIC A6/02 WEF 15 JUN 2002  
AIC A8/02 WEF 28 NOV 2002  
AIC A1/04 WEF 1 APR 2004  
AIC A1/05 WEF 1 APR 2005  
AIC A2/05 WEF 1 JUL 2005  
AIC A5/05 WEF 15 JAN 2006  
AIC A1/06 WEF 1 JAN 2006  
AIC A1/07 WEF 1 FEB 2007  
AIC A2/07 WEF 1 FEB 2007  
AIC A3/07 WEF 1 FEB 2007  
AIC A4/07 WEF 1 FEB 2007  
AIC A5/07 WEF 1 SEP 2007  
AIC A6/07 WEF 1 SEP 2007  
AIC A7/07 WEF 1 SEP 2007  
AIC A10/07 WEF 11 DEC 2007  
AIC A1/09 WEF 1 JAN 2009  
AIC A2/09 WEF 15 JAN 2009  
AIC A1/12 WEF 1 JUL 2012  
AIC A2/12 WEF 1 NOV 2012  
AIC A3/12 WEF 1 NOV 2012  
AIC A1/13 WEF 1 MAY 2013  
AIC A1/14 WEF 01 AUG 2014  
AIC A2/14 WEF 20 OCT 2014  
AIC A2/16 WEF 23 JUN 2016  
AIC A3/18 WEF 01 MAR 2018  
AIC A3/19 WEF 28 MAR 2019  
AIC A1/20 WEF 01 JAN 2020  
AIC A2/20 WEF 01 JAN 2020  
AIC A3/20 WEF 3 JAN 2020