

**Tel: +95 (0)1 533080**  
**Tel: +95 (0)1 533030-039**  
**AFS:VYYYYOYX VYYYYNYX**  
**Fax: +95 (0)1 533085/533016**  
**E-Mail: aiso@ais.gov.mm**

Department of Civil Aviation  
**International NOTAM Office**  
ATC Operations Building  
Yangon International Airport, Yangon 11021  
Myanmar

**NOTAM LIST**  
**Series A**

**02 Jan 2019**

THE FOLLOWING NOTAM A SERIES ARE **STILL IN FORCE ON 02 January 2019 04:30:50 UTC**. NOTAM NOT INCLUDED IN THIS LIST HAVE EITHER BEEN CANCELLED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

## **NOF: VYYY / SERIES A**

### **ENROUTE / GENERAL**

#### **VYYF(YANGON FIR)**

##### **A0010/18**

From 1801160555 to PERM

NOTAMR A0054/17

E) THE FOLLOWING AIRPORTS HAVE/DO NOT HAVE THE NIGHT LANDING FACILITIES

AA)AIRPORTS WITH NIGHT LANDING FACILITIES ARE:

VYAN, VYAS, VYBG, VYBM, VYDW, VYHH, VYKG,  
VYKT, VYLK, VYLS, VYMD, VYME, VYMK, VYMW,  
VYNT, VYPN, VYSW, VYTD, VYTL, VYYY.

BB)AIRPORTS WIITHOUT NIGHT LANDING FACILITIES ARE:

VYBP, VYHL, VYKI, VYKL, VYKP, VYKU, VYMM,  
VYMN, VYMS, VYMY, VYPA, VYPT, VYPU.

CC)AIRPORTS WITH SERVICE MESSAGE VOR/DME:

VYBG, VYCZ, VYDW, VYHH, VYKG, VYLS, VYMD, VYMK,  
VYNT, VYPN, VYSW, VYTD, VYTO, VYTL, VYYY.

##### **A0189/18**

From 1809130001 to PERM

NOTAMN

E) REFER TO AIRAC AMENDMENT 03/2018 AERONAUTICAL INFORMATION PUBLICATION PAGE EN ROUTE 5.2-2, THREE AIR SPACES WITHOUT DESIGNATORS FOLLOWING VYR26 MAUBIN (AN AIR SPACE OF DEFINED DIMENSION BETWEEN BEARINGS 240 DEGREES TRUE AND 265 DEGREES TRUE AND ARCS BETWEEN 30NM AND 50 NM FROM MINGALADON AIR-REPORT 165426.16N 0960759.66E) ARE REMOVED.

**Lower Limit:** 8000 FT AMSL      **Upper Limit:** FL 160

##### **A0225/18**

From 1810120110 to 1810120840EST

NOTAMN

D) BTN 0110/0840 UTC ON 12 OCT 2018

E) GUNFIRING EXERCISE WILL TAKE PLACE WITH THE FOLLOWING  
DETAILS:THE COORDS OF THE DANGER ZONES ARE AS FOLLOWS:

DANGER ZONE (KONDE-NANTKHON)

COORDINATES: POINT(A) 211500N 0964600E

POINT(B) 211500N 0965200E

POINT(C) 212000N 0964600E

POINT(D) 212000N 0952000E  
POINT(A) 211500N 0964600E  
NO OVERFLYING ACTIVITY IS PERMISSIBLE WITHIN  
THE ABOVE MENTIONED DANGER ZONE .

**Lower Limit:** GND      **Upper Limit:** 22000 FT AGL

**A0252/18**

From 1901030000 to 1901162359

NOTAMN

E) TRIGGER A NOTICE DISTRIBUTED BY MEANS OF TELECOMMUNICATION CONTAINING INFORMATION CONCERNING THE ESTABLISHMENT, CONDITION OR CHANGE IN ANY AERONAUTICAL FACILITY, SERVICE, PROCEDURE OR HAZARD, THE TIMELY KNOWLEDGE OF WHICH IS ESSENTIAL TO PERSONNEL CONCERNED WITH FLIGHT OPERATIONS - PERMANENT AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 04/2018 EFFECTIVE FROM 03 JANUARY 2019.

**A0293/18**

From 1901080000 to 1901291130

NOTAMN

D) BTN 0000/1130 ON 08,13,21,25,29 JAN 2019

E) GUN FIRING EXERCISE WILL TAKE PLACE WITH THE FOLLOWING DETAILS:

THE COORDINATES OF DANGER ZONE(BA YINT NAUNG) AS FLW

POINT(A) 204000N 0953000E

POINT(B) 204000N 0955000E

POINT(C) 205000N 0953000E

POINT(D) 205000N 0955000E

POINT(A) 204000N 0953000E

NO OVERFLYING PERMISSIBLE WITHIN THE ABOVE  
MENTIONED DANGER ZONE.

DURING THE HOURS OF ACTIVITY, THE FOLLOWING AIR TRAFFIC SERVICES ROUTE IS  
NOT AVBL IN YANGON FIR.

01) W-15 NOT AVBL.

**Lower Limit:** GND      **Upper Limit:** 30000FT AGL

**A0296/18**

From 1812300130 to 1901310900

NOTAMN

D) BTN 0130/0900 FROM 30 DEC 2018 TO

31 JAN 2019

E) GUN FIRING EXERCISE WILL TAKE PLACE WITH THE FOLLOWING DETAILS:

THE COORDINATES OF DANGER ZONE(MONDAING) AS FLW

POINT(A) 204000N 0953000E

POINT(B) 204000N 0955000E

POINT(C) 205000N 0953000E

POINT(D) 205000N 0955000E

POINT(A) 204000N 0953000E

NO OVERFLYING PERMISSIBLE WITHIN THE ABOVE  
MENTIONED DANGER ZONE.

DURING THE HOURS OF ACTIVITY, THE FOLLOWING AIR TRAFFIC SERVICES ROUTE IS  
NOT AVBL IN YANGON FIR.

01) W-15 NOT AVBL.

**Lower Limit:** GND      **Upper Limit:** 30000FT AGL

**A0001/19**

From 1901010003 to 1902010003EST

NOTAMR A0261/18

E) CHECKLIST

YEAR=2018 0010 0189 0225 0232 0247 0249 0252 0253 0254 0255 0256 0258

0264 0265 0275 0278 0286 0290 0291 0293 0294 0295 0296

LATEST PUBLICATIONS

AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 4/18 EFFECTIVE FROM 03 JANUARY 2019

AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 18/19 EFFECTIVE FROM 03 JANUARY 2019

AIP AMENDMENT 2/17 EFFECTIVE FROM 15 MARCH 2017

AIP SUPPLEMENT 5/17 EFFECTIVE FROM 2 FEBRUARY 2017

AIC A3/18 EFFECTIVE FROM 01 MARCH 2018

## **AERODROMES**

### **VYNT(NAYPYITAW INTL)**

#### **A0256/18**

From 1901030000 to 1901162359

NOTAMN

E) TRIGGER A NOTICE DISTRIBUTED BY MEANS OF TELECOMMUNICATION CONTAINING INFORMATION CONCERNING THE ESTABLISHMENT, CONDITION OR CHANGE IN ANY AERONAUTICAL FACILITY, SERVICE, PROCEDURE OR HAZARD, THE TIMELY KNOWLEDGE OF WHICH IS ESSENTIAL TO PERSONNEL CONCERNED WITH FLIGHT OPERATIONS - AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 14/2018 EFFECTIVE FROM 03 JANUARY 2019.

ESTABLISHMENT OF PERFORMANCE-BASED NAVIGATION PROCEDURES AT NAYPYITAW INTERNATIONAL AIRPORT

AND AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 15/2018 EFFECTIVE FROM 03 JANUARY 2019.

ESTABLISHMENT OF ILS APPROACH PROCEDURE AT NAYPYITAW INTERNATIONAL AIRPORT.

#### **A0290/18**

From 1812260343 to 1901231030

NOTAMN

D) BTN 0230 /1030 ON 26 DEC 2018 TO 23 JAN 2019

E) VYNT INTERNATIONAL A/P CONCRETE CUTTING WIP AT TAXIWAY A1 TAXIWAY A3

AND TAXIWAY A6 PILOT EXERCISE CAUTION LANDING AND EXERCISE CAUTION TAKE-OFF .

#### **A0291/18**

From 1812260350 to 1901231030

NOTAMN

D) BTN 0230/1030 ON 26 DEC 2018 TO 23 JAN 2019

E) VYNT INTERNATIONAL A/P AIR FIELD DRINAGE SYSTEM REPAIRING

WIP PILOT EXERCISE CAUTION LANDING AND EXERCISE CAUTION TAKE-OFF .

### **VYCZ(MANDALAY/CHANMYATHAZI)**

#### **A0275/18**

From 1812120524 to 1903112359EST

NOTAMR A0208/18

E) VYCZ AD VOR 112.8 MHZ AND DME U/S DUE TO TECHNICAL REASON.

### **VYSW(SITTWE)**

#### **A0253/18**

From 1901030000 to 1901162359

NOTAMN

E) TRIGGER A NOTICE DISTRIBUTED BY MEANS OF TELECOMMUNICATION CONTAINING INFORMATION CONCERNING THE ESTABLISHMENT, CONDITION OR CHANGE IN ANY AERONAUTICAL FACILITY, SERVICE, PROCEDURE OR HAZARD, THE TIMELY KNOWLEDGE OF WHICH IS ESSENTIAL TO PERSONNEL CONCERNED WITH FLIGHT OPERATIONS - AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 18/2018 EFFECTIVE FROM 03 JANUARY 2019.

ESTABLISHMENT OF PERFORMANCE-BASED NAVIGATION PROCEDURES AT SITTWE AIRPORT.

**VYYY(YANGON INTL)**

**A0232/18**

From 1810170001 to 1901162359EST

NOTAMN

D) DLY

E) VYYY AD RAPID EXIT TAXIWAY R1 AND EXIT TAXIWAY A2 WILL BE CLOSED DUE TO WIP.

**A0247/18**

From 1811201730 to 1901301729

NOTAMN

D) DLY

E) VYYY AD APRON(A) AIRCRAFT STAND NO-7 WILL BE CLOSED DUE TO RENOVATION WIP.

**A0249/18**

From 1811221945 to 1902212300

NOTAMR A0248/18

D) BTN 1945/2300 ON MON,TUE,WED,THU,FRI,SUN  
AND 2030/2300 ON SAT

E) VYYY AD TWY-A1 WILL BE CLOSED DUE STOP BAR AND RWY  
GUARD LIGHT RELOCATION WIP.

**A0258/18**

From 1811300001 to 1903012359EST

NOTAMR A0188/18

E) VYYY AD TAXIWAY A BETWEEN EXIT WAY A AND B  
TWY LIGHTING WILL BE TEMPORARY INSTALLED AT RWY  
EDGE(ON THE EDGE LINE)DUE TO TAXIWAY EXPANSION WORK.

**A0264/18**

From 1812051945 to 1901042300

NOTAMR A0263/18

D) BTN 1945/2300 (MON,TUE,WED,THUR,FRI,SUN)  
2030/2300 (ONLY SATURDAY)

E) VYYY AD EAST AND WEST SIDE OF TAXIWAY A , HOLES OPEN 0.45 FEETS  
DEEP WITH DIMENSION (15 MINIMUM VALUE OF RUNWAY VISUAL RANGE X 100 M) DUE TO CONSTRUCTION  
OF ISOLATED

ACFT PARKING POSITION WIP . LOCATION BETWEEN TAXIWAY A 6 AND TAXIWAY A 5 ,400 MINIMUM  
VALUE OF RUNWAY VISUAL RANGE FROM

TWY A 5 CENTRE LINE AND AT THE EDGE OF TAXIWAY A .

ALL ACFTS ARE EXERCISE CAUTION TAXI .

**A0265/18**

From 1812051945 to 1902262300

NOTAMR A0251/18

D) BTN 1945/2300 UTC FROM 27 NOV 2018

TO 26 FEB 2019

E) VYYY AD RUNWAY AND TAXIWAY SURFACE REPAIRING WORK AND PAINTING WORK WILL BE DONE NIGHT TIME.

**A0278/18**

From 1812150130 to 1903141130

NOTAMN

E) VYYY AD RUNWAY 21 APPROACH LIGHTING SYSTEM WITH SEQUENTIAL FLASHING LIGHTS REPLACEMENT WIP.

**A0286/18**

From 1812220130 to 1902211130

NOTAMR A0285/18

D) BTN 0130/1130

E) RUNWAY 03 SIMPLE APPROACH LIGHTING SYSTEM RENOVATION WIP.

**A0295/18**

From 1812290001 to 1903282359

NOTAMR A0223/18

E) VYYY AD RWY-21 TOUCHDOWN ZONE FRICTION LEVEL IS UNDER MINIMUM FRICTION BELOW 0.5 WHEN WET CONDITION. PILOT EXERCISE CAUTION LANDING AND TAKE-OFF.

**VYBG(BAGAN / NYAUNG U)**

**A0255/18**

From 1901030000 to 1901162359

NOTAMN

E) TRIGGER A NOTICE DISTRIBUTED BY MEANS OF TELECOMMUNICATION CONTAINING INFORMATION CONCERNING THE ESTABLISHMENT, CONDITION OR CHANGE IN ANY AERONAUTICAL FACILITY, SERVICE, PROCEDURE OR HAZARD, THE TIMELY KNOWLEDGE OF WHICH IS ESSENTIAL TO PERSONNEL CONCERNED WITH FLIGHT OPERATIONS - AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 16/2018 EFFECTIVE FROM 03 JANUARY 2019. ESTABLISHMENT OF PERFORMANCE-BASED NAVIGATION PROCEDURES AT BAGAN/NYAUNG UPWARD AIRPORT.

**VYHH(HEHO)**

**A0254/18**

From 1901030000 to 1901162359

NOTAMN

E) TRIGGER A NOTICE DISTRIBUTED BY MEANS OF TELECOMMUNICATION CONTAINING INFORMATION CONCERNING THE ESTABLISHMENT, CONDITION OR CHANGE IN ANY AERONAUTICAL FACILITY, SERVICE, PROCEDURE OR HAZARD, THE TIMELY KNOWLEDGE OF WHICH IS ESSENTIAL TO PERSONNEL CONCERNED WITH FLIGHT OPERATIONS - AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 17/2018 EFFECTIVE FROM 03 JANUARY 2019. ESTABLISHMENT OF PERFORMANCE-BASED NAVIGATION PROCEDURES AT HEHO AIRPORT.

**VYMD(MANDALAY INTL)**

**A0294/18**

From 1901010130 to 1901312330

NOTAMN

D) BTN 0130/2330 ON 01 TO 31 JAN 2019

E) VYMD AD TAXIWAY A SHOULDER 7000 X 100 FEET REPAIRING

WORK IN PROGRESS BESIDE RUNWAY 17 WORK IN PROGRESS

PILOT EXERCISE CAUTION LANDING AND EXERCISE CAUTION TAKE-OFF

---

### **Latest AIP Amendments:**

AIRAC AIP AMDT 4/18 WEF 03 JAN 2019

AIP AMDT 1/19 WEF 14 JAN 2019

### **AIP Supplements in force:**

AIRAC AIP SUP 1/03 WEF 27 NOV 2003

AIRAC AIP SUP 6/04 WEF 25 NOV 2004

AIRAC AIP SUP 31/09 WEF 17 DEC 2009

AIRAC AIP SUP 2/15 WEF 12 NOV 2015

AIRAC AIP SUP 6/17 WEF 20 JUL 2017

AIRAC AIP SUP 8/17 WEF 07 DEC 2017

AIRAC AIP SUP 4/18 WEF 29 MAR 2018

AIRAC AIP SUP 7/18 WEF 08 NOV 2018

AIRAC AIP SUP 8/18 WEF 08 NOV 2018

AIRAC AIP SUP 9/18 WEF 08 NOV 2018

AIRAC AIP SUP 10/18 WEF 08 NOV 2018

AIRAC AIP SUP 11/18 WEF 06 DEC 2018

AIRAC AIP SUP 12/18 WEF 06 DEC 2018

AIRAC AIP SUP 13/18 WEF 06 DEC 2018

AIRAC AIP SUP 14/18 WEF 03 JAN 2019

AIRAC AIP SUP 15/18 WEF 03 JAN 2019

AIRAC AIP SUP 16/18 WEF 03 JAN 2019

AIRAC AIP SUP 17/18 WEF 03 JAN 2019

AIRAC AIP SUP 18/19 WEF 03 JAN 2019

AIP SUP 5/04 WEF 1 SEP 2004

AIP SUP 3/05 WEF 1 SEP 2005

AIP SUP 2/11 WEF 30 MAY 2011

AIP SUP 3/11 WEF 30 MAY 2011

AIP SUP 4/11 WEF 30 MAY 2011

AIP SUP 1/13 WEF 1 AUG 2013

AIP SUP 2/13 WEF 1 AUG 2013

AIP SUP 3/13 WEF 1 AUG 2013

AIP SUP 4/13 WEF 1 AUG 2013

AIP SUP 5/13 WEF 1 AUG 2013

AIP SUP 6/13 WEF 1 AUG 2013

AIP SUP 8/13 WEF 1 AUG 2013

AIP SUP 9/13 WEF 1 AUG 2013

AIP SUP 10/13 WEF 1 AUG 2013

AIP SUP 13/13 WEF 1 AUG 2013

AIP SUP 14/13 WEF 1 AUG 2013

AIP SUP 15/13 WEF 1 AUG 2013

AIP SUP 16/13 WEF 1 AUG 2013

AIP SUP 17/13 WEF 1 AUG 2013

AIP SUP 18/13 WEF 1 AUG 2013

AIP SUP 1/17 WEF 2 FEB 2017

AIP SUP 2/17 WEF 2 FEB 2017

AIP SUP 3/17 WEF 2 FEB 2017

AIP SUP 4/17 WEF 2 FEB 2017

AIP SUP 5/17 WEF 2 FEB 2017

### **AICs in force:**

AIC A6/02 WEF 15 JUN 2002  
AIC A8/02 WEF 28 NOV 2002  
AIC A1/04 WEF 1 APR 2004  
AIC A1/05 WEF 1 APR 2005  
AIC A2/05 WEF 1 JUL 2005  
AIC A5/05 WEF 15 JAN 2006  
AIC A1/06 WEF 1 JAN 2006  
AIC A1/07 WEF 1 FEB 2007  
AIC A2/07 WEF 1 FEB 2007  
AIC A3/07 WEF 1 FEB 2007  
AIC A4/07 WEF 1 FEB 2007  
AIC A5/07 WEF 1 SEP 2007  
AIC A6/07 WEF 1 SEP 2007  
AIC A7/07 WEF 1 SEP 2007  
AIC A10/07 WEF 11 DEC 2007  
AIC A1/09 WEF 1 JAN 2009  
AIC A2/09 WEF 15 JAN 2009  
AIC A1/12 WEF 1 JUL 2012  
AIC A2/12 WEF 1 NOV 2012  
AIC A3/12 WEF 1 NOV 2012  
AIC A1/13 WEF 1 MAY 2013  
AIC A1/14 WEF 01 AUG 2014  
AIC A2/14 WEF 20 OCT 2014  
AIC A2/16 WEF 23 JUN 2016  
AIC A3/18 WEF 01 MAR 2018  
AIC A1/19 WEF 01 JAN 2019  
AIC A2/19 WEF 01 JAN 2019