

Tel: +95 (0)1 533080
Tel: +95 (0)1 533030-039
AFS:VYYYYOYX VYYYYNYX
Fax: +95 (0)1 533085/533016
E-Mail: aiso@ais.gov.mm

Department of Civil Aviation
International NOTAM Office
ATC Operations Building
Yangon International Airport, Yangon 11021
Myanmar

NOTAM LIST
Series A

01 Jun 2018

THE FOLLOWING NOTAM A SERIES ARE **STILL IN FORCE ON 01 June 2018 04:17:10 UTC**. NOTAM NOT INCLUDED IN THIS LIST HAVE EITHER BEEN CANCELLED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN AIP.

NOF: VYYY / SERIES A

ENROUTE / GENERAL

VYYF(YANGON FIR)

A0010/18

From 1801160555 to PERM

NOTAMR A0054/17

E) THE FOLLOWING AIRPORTS HAVE/DO NOT HAVE THE NIGHT LANDING FACILITIES

AA)AIRPORTS WITH NIGHT LANDING FACILITIES ARE:

VYAN, VYAS, VYBG, VYBM, VYDW, VYHH, VYKG,
VYKT, VYLK, VYLS, VYMD, VYME, VYMK, VYMW,
VYNT, VYPN, VYSW, VYTD, VYTL, VYYY.

BB)AIRPORTS WIITHOUT NIGHT LANDING FACILITIES ARE:

VYBP, VYHL, VYKI, VYKL, VYKP, VYKU, VYMM,
VYMN, VYMS, VYMY, VYPA, VYPT, VYPU.

CC)AIRPORTS WITH SERVICE MESSAGE VOR/DME:

VYBG, VYCZ, VYDW, VYHH, VYKG, VYLS, VYMD, VYMK,
VYNT, VYPN, VYSW, VYTD, VYTO, VYTL, VYYY.

A0084/18

From 1805290130 to 1806060830

NOTAMN

D) BTN 0130/0830 ON 29 MAY TO 06 JUNE 2018

E) X COUNTRY LOW FLYING FORMATION EXERCISE

CARRIED OUT BY F-7 ACFT.ROUTE WILL BE,

MINGALARDON-TOEKUN-DARPYACAUNG-

VYPN-MINGALARDON

ALL AIRCRAFT AND HELICOPTER AVOID IN THIS AREA.

Lower Limit: GND

Upper Limit: 6000FT AGL

A0087/18

From 1805240000 to 1806072359

NOTAMN

E) I HAVE NOTHING TO SEND TO YOU AERONAUTICAL INFORMATION REGULATION AND CONTROL FOR EFFECTIVE DATE 24 MAY 2018

A0091/18

From 1805292330 to 1806011130

NOTAMN

D) BTN 2330/1130 ON 29,30,31 MAY 2018 AND 01 JUN 2018

E) GROUND TO AIR GUN FIRING EXERCISE WILL TAKE PLACE AT MALUN AREA
FIRING RANGE AT FOLLOW COORD:

1940N TO 2000N

09430E TO 09510E

ALL AIRCRAFT AND HELICOPTER AVOID MALUN AREA.

Lower Limit: GND **Upper Limit:** 48000FT AGL

A0094/18

From 1806050130 to 1806130900

NOTAMN

D) BTN 0130/0900 FM 05 JUN 2018 TO 13 JUN 2018

E) MYANMAR AIR FORCE F7 AIRCRAFT AIR TO GROUND GUN FIRING EXERCISE WILL TAKE PLACE
AT HTANTABIN AREA AS FOLLOWING BOUNDED COORD

1852N TO 1855N

09631E TO 09634E

ALL AIRCRAFT AND HELICOPTER AVOID IN HTANTABIN AREA.

Lower Limit: GND **Upper Limit:** 15000FT AGL

A0095/18

From 1806010003 to 1807010003EST

NOTAMR A0076/18

E) CHECKLIST

YEAR=2017 0150

YEAR=2018 0010 0039 0042 0056 0063 0064 0067 0069 0071 0075 0077 0080

0081 0083 0084 0087 0088 0090 0091 0094

LATEST PUBLICATIONS

AIRAC AERONAUTICAL INFORMATION PUBLICATION AMENDMENT 2/18 EFFECTIVE FROM 29 MARCH 2018

AIRAC AERONAUTICAL INFORMATION PUBLICATION SUPPLEMENT 4/18 EFFECTIVE FROM 29 MARCH 2018

AIP AMENDMENT 2/17 EFFECTIVE FROM 15 MARCH 2017

AIP SUPPLEMENT 5/17 EFFECTIVE FROM 2 FEBRUARY 2017

AIC A3/18 EFFECTIVE FROM 01 MARCH 2018

AERODROMES

VYNT(NAYPYITAW INTL)

A0056/18

From 1803271059 to 1806262359EST

NOTAMN

E) VYNT AD AWOS U/S DUE TECHNICAL REASON

A0067/18

From 1804180830 to 1807172359EST

NOTAMN

E) VYNT INT'L A/P RUNWAY AND TAXIWAY MARKING PAINTING WIP.

REMARKS-DURING OUTSIDE OPERATION HOUR AT DAY AND NIGHT.

VY CZ(MANDALAY/CHANMYATHAZI)

A0042/18

From 1803140001 to 1806132359EST
NOTAMR A0193/17
E) VYZ AD VOR 112.8 MHZ AND DME U/S DUE TO TECHNICAL REASON

VYYY(YANGON INTL)

A0150/17

From 1709110930 to PERM
NOTAMR A0137/17
E) VYYY AD NEW APRON (B) RIGHT SIDE OF RUNWAY 21, WILL BE SATRT USING
FOR DOMESTIC AIRLINES NIGHT PARKING APRON(B) TOTAL AREA IS 58786 SQM.COORDINATE POINTS
ARE N165357.845 E0960730.771,N165403.877 E0960734.876,N165404.841 E0960733.351,N165413.630
E0960739.342,N165411.338 E0960743.006,N165356.339 E0960732.796 RESPECTIVELY

A0039/18

From 1803070530 to 1806061930
NOTAMN
D) BTN 2330/1930 UTC DLY
E) VYYY AD RUNWAY EDGE LIGHTING WILL BE TEMPORARY INSTALLED
AT THE RUNWAY EDGE LINE MARKING DURING RWY
SHOULDER CONSTRUCTION

A0064/18

From 1804060632 to 1807062230
NOTAMN
D) BTN 0030/1230 UTC (DAY TIME)
1530/2230 UTC (NIGHT TIME)
E) GSE PARKING WORK IN PROGRESS AT NOTHERN
EDGE OF APRON(A),NEAR OLD CONTROL TOWER

A0071/18

From 1804240410 to 1807232359EST
NOTAMN
E) PRECISION APPROACH PATH INDICATOR ON RIGHT SIDE OF RUNWAY 21 WITHDRAWN
DUE EXTENDING RUNWAY LIGHTING SYSTEM WIP LEFT SIDE
PRECISION APPROACH PATH INDICATOR ONLY AVBL.

A0075/18

From 1805010001 to 1808312359EST
NOTAMR A0019/18
E) VYYY AD TAXIWAY A BETWEEN EXIT WAY A AND B
TWY LIGHTING WILL BE TEMPORARY INSTALLED AT RWY
EDGE(ON THE EDGE LINE)DUE TO TAXIWAY EXPANSION WORK.

A0077/18

From 1805040506 to 1807222030
NOTAMR A0068/18
D) BTN 0030/2030 DLY
E) INSET TYPE OF OBSTRUCTION LIGHT WILL INSTALL NEAR
APRON-A PRAKING NO-108 AND NO-109 WHICH IS UNSERVICEABLE
MARKING AREA.

A0088/18

From 1805221242 to 1808212359EST
NOTAMR A0030/18
E) YANGON AIRPORT TERMINAL (1) NEW SAFE DOCK
STOP LINES AND LOCATIONS AS FOLLOWS :
FIXED GATE STAND NO.8
(1) 165414.92N0960806.76E A321, B737-700/800/900
(2) 165414.75N0960806.39E A319, A320,E190, E170, B737-300/400

A0090/18

From 1805281930 to 1808282300
NOTAMR A0032/18
D) BTN 1930/2300 ON 28 MAR TO 28 AUG 2018
E) VYYY AD RUNWAY AND TAXIWAY SURFACE REPAIRING WORK
AND PAINTING WORK WILL BE DONE NIGHT TIME

VYMD(MANDALAY INTL)

A0063/18

From 1804051022 to 1807042359EST
NOTAMR A0002/18
E) VYMD AD GROUND FREQUENCY 121.85 MHZ AND
ATIS 128.5 MHZ U/S DUE TO TECHNICAL REASON.

A0069/18

From 1804200926 to 1807192359EST
NOTAMN
E) VYMD AD SOUTHERN PART OF TAXIWAY LIGHTING
U/S DUE TO TECH PROBLEM.

A0080/18

From 1805130001 to 1808122359EST
NOTAMR A0023/18
E) VYMD AD GROUND FREQUENCY 121.85 MHZ AND
ATIS 128.5 MHZ U/S DUE TO TECHNICAL REASON

A0081/18

From 1805200000 to 1808192359EST
NOTAMN
E) VYMD AD SOUTHERN PART OF TAXIWAY 35A CLOSED BEYOND
A3 TO STOP-END OF TAXIWAY 35 DUE TO TAXIWAY CRACKS REPAIRING
WIP

A0083/18

From 1805200001 to 1806202359
NOTAMN
D) BTN 0001/2359 DLY
E) MANDALAY INTERNATIONAL AIRPORT, SOUTHERN PART OF TAXIWAY WILL BE CLOSED BEYOND TWY-
A3 TO
END OF TWY-35 DUE TWY-35A CRACKS REPAIRING WORK.

Latest AIP Amendments:

AIRAC AIP AMDT 2/18 WEF 29 MAR 2018

AIP Supplements in force:

AIRAC AIP SUP 1/03 WEF 27 NOV 2003
AIRAC AIP SUP 6/04 WEF 25 NOV 2004
AIRAC AIP SUP 31/09 WEF 17 DEC 2009
AIRAC AIP SUP 2/15 WEF 12 NOV 2015
AIRAC AIP SUP 3/15 WEF 10 DEC 2015
AIRAC AIP SUP 4/15 WEF 10 DEC 2015
AIRAC AIP SUP 6/17 WEF 20 JUL 2017
AIRAC AIP SUP 8/17 WEF 07 DEC 2017
AIRAC AIP SUP 1/18 WEF 29 MAR 2018
AIRAC AIP SUP 2/18 WEF 29 MAR 2018
AIRAC AIP SUP 3/18 WEF 29 MAR 2018
AIRAC AIP SUP 4/18 WEF 29 MAR 2018
AIP SUP 5/04 WEF 1 SEP 2004
AIP SUP 3/05 WEF 1 SEP 2005
AIP SUP 2/11 WEF 30 MAY 2011
AIP SUP 3/11 WEF 30 MAY 2011
AIP SUP 4/11 WEF 30 MAY 2011
AIP SUP 1/13 WEF 1 AUG 2013
AIP SUP 2/13 WEF 1 AUG 2013
AIP SUP 3/13 WEF 1 AUG 2013
AIP SUP 4/13 WEF 1 AUG 2013
AIP SUP 5/13 WEF 1 AUG 2013
AIP SUP 6/13 WEF 1 AUG 2013
AIP SUP 7/13 WEF 1 AUG 2013
AIP SUP 8/13 WEF 1 AUG 2013
AIP SUP 9/13 WEF 1 AUG 2013
AIP SUP 10/13 WEF 1 AUG 2013
AIP SUP 13/13 WEF 1 AUG 2013
AIP SUP 14/13 WEF 1 AUG 2013
AIP SUP 15/13 WEF 1 AUG 2013
AIP SUP 16/13 WEF 1 AUG 2013
AIP SUP 17/13 WEF 1 AUG 2013
AIP SUP 18/13 WEF 1 AUG 2013
AIP SUP 2/16 WEF 1 JAN 2016
AIP SUP 1/17 WEF 2 FEB 2017
AIP SUP 2/17 WEF 2 FEB 2017
AIP SUP 3/17 WEF 2 FEB 2017
AIP SUP 4/17 WEF 2 FEB 2017
AIP SUP 5/17 WEF 2 FEB 2017

AICs in force:

AIC A6/02 WEF 15 JUN 2002
AIC A8/02 WEF 28 NOV 2002
AIC A1/04 WEF 1 APR 2004
AIC A1/05 WEF 1 APR 2005
AIC A2/05 WEF 1 JUL 2005
AIC A5/05 WEF 15 JAN 2006
AIC A1/06 WEF 1 JAN 2006
AIC A1/07 WEF 1 FEB 2007
AIC A2/07 WEF 1 FEB 2007
AIC A3/07 WEF 1 FEB 2007
AIC A4/07 WEF 1 FEB 2007
AIC A5/07 WEF 1 SEP 2007
AIC A6/07 WEF 1 SEP 2007
AIC A7/07 WEF 1 SEP 2007

AIC A10/07 WEF 11 DEC 2007
AIC A1/09 WEF 1 JAN 2009
AIC A2/09 WEF 15 JAN 2009
AIC A1/12 WEF 1 JUL 2012
AIC A2/12 WEF 1 NOV 2012
AIC A3/12 WEF 1 NOV 2012
AIC A1/13 WEF 1 MAY 2013
AIC A2/14 WEF 20 OCT 2014
AIC A2/16 WEF 23 JUN 2016
AIC A1/18 WEF 1 JAN 2018
AIC A2/18 WEF 1 JAN 2018
AIC A3/18 WEF 01 MAR 2018